

Horizontal Band saw Cleaning Procedure

1. From top to bottom, use the hand broom to brush all large shavings off machine onto the floor
2. Use rag to soak up oil and coolant
3. Sweep up shavings off of floor
4. Vacuum all remaining shavings (on and off machine)
5. Lightly coat metal parts with WD40 to protect from rusting.
6. If oil or coolant is spilled on the floor mop around machine.
7. Scan 360 degrees around machine repeat above steps if necessary

